

Imray Correction Notice ICG40-1

4 January 2024

Chart **G40** WGS 84

Edition 2014

Versions available:

New Edition (corrected to June 2014)

Update (corrected to March 2020)

Update (corrected to January 2022)

Update (corrected to January 2023)

Update (corrected to January 2024)

NOTES

Below is a complete list of corrections issued since the 2014 edition of this chart was published.

Each correction is issued with an ILNW reference number and year.

Corrections are listed chronologically in ascending order.

For Update versions of this chart, please check the bottom left corner of the chart to determine the last applied correction.

Any further corrections will be applicable from that point onwards.

1 **Antalya Celebi Marina, Military Quay (Plan D)**

Insert dangerous Wk symbol in 36°49'·76N 30°36'·46E. (ILNW 97/15)

2 **Kaş W, Bucak Denizi**

Insert Lt FI(2)5s5M in 36°11'·66N 29°35'·10E. (ILNW 300/15)

3 **Antalya Körfezi**

Numerous firing practice areas exist within Antalya Körfezi, all outside the 200m depth contour.

Further details will be included in the next edition of this chart. (ILNW 488/16)

4 **Antalya Körfezi**

Insert Y special spher Lt buoy FI(5)Y.20s in 36°44'·3N 31°00'·2E (ILNW 650/18)

5 **Kekova Adasi S (Plan A)**

Insert BRB isolated danger pillar Lt buoy FI(2)10s in 36°09'·93N 29°52'·18E (ILNW 67/20)

6 **Kekova Adasi (Plan B)**

Insert BY N cardinal pillar Lt buoy Q in 36°10'·34N 29°50'·50E (ILNW 68/20)

7 **Antalya Celebi Marina**

Amend range of Lt FI.R.&FI.G.3s6M to 7M in 36°50'·04N 30°36'·94E (ILNW 69/20)

8 **Antalya Celebi Marina (Plan D)**

Amend range of Lt:

FI.R.3s12m6M to 7M in 36°50'·04N 30°36'·99E

FI.G.3s15m6M to 7M in 36°50'·08N 30°36'·75E (ILNW 69/20)

9 **Baba Burnu**

Amend range of Lt FI.5s35m14M to 10M in 36°50'·77N 30°45'·48E. AIS remains unchanged. (ILNW 624/21)

10 **Kekova Roads (Plan A)**

Move S cardinal pillar Lt buoy Q(6)+LFI.15s in 36°11'·31N 29°51'·83E to 36°11'·24N 29°51'·78E and add racon sym & assoc. lgd AIS at buoy. (ILNW 504/22)

11 **Kekova Adasi (Plan B)**

Move N cardinal pillar Lt buoy Q in 36°10'·34N 29°50'·50E to 36°10'·36N 29°50'·50E (ILNW 504/22)

12 **Kemer (Plan E)**

Insert BYB E cardinal pillar Lt buoy Q(3)10s in 36°36'·05N 30°34'·76E (ILNW 505/22)

13 Approaches to Antalya (Plan D)

Replace mooring buoy with Y special purpose can Lt buoy:

F.Y.3s in 36°49'·82N 30°37'·05E

F.Y.3s in 36°49'·80N 30°36'·94E

F.Y.3s in 36°49'·65N 30°37'·03E

F.Y.4s in 36°49'·57N 30°36'·80E

F.Y.4s in 36°49'·54N 30°36'·69E

F.Y.4s in 36°49'·40N 30°36'·78E (ILNW 270/23)

14 Approaches to Antalya Celebi Marina

Delete Y pillar Lt buoy Fl.Y.3s in 36°47'·60N 30°36'·65E

Y spar Lt buoy Fl.Y.3s in:

36°48'·64N 30°35'·67E

36°48'·43N 30°36'·37E

36°48'·23N 30°36'·47E

36°48'·04N 30°36'·07E (ILNW 308/23)

15 Kemer (Main chart & Plan E)

Main chart

Amend Lt Fl.G&Fl.R.3M to Fl(2)G&Fl(2)R.7s5M in 36°36'·27N 30°34'·36E

Plan E

Amend Lt:

Fl.G.3s11m3M to Fl(2)G.7s5M in 36°36'·06N 30°34'·32E

Fl.R.3s11m3M to Fl(2)R.7s5M in 36°36'·12N 30°34'·35E (ILNW 319/23)